

This form is used to describe how the accident happened. It does not mean that anyone admits liability. Please have it completed by both drivers.

1. Date of accident

2026-05-14

Time

17:20

2. Place

Profsoyuznaya ulytsa 42, Moskva, RU

VEHICLE A

6. Policyholder/Insured

(see insurance certificate)

Surname

Yvanov

First name

Yvan

Address

Profsoyuznaya ulytsa 42, Moskva

Postcode

117420

Country

RU

Phone/ email

+7 916 123-45-67

7.1 Motor vehicle

Make, type

Kia Sportage

Registration number

A447KM 77

Country of registration

RU

7.2 Trailer

Registration number

Country of registration

8. Insurance company

(see insurance certificate)

Company name

SPAO "Ynhosstrakh"

Policy number

RU-2026-778120

Green Card number

RU/26/778120

Insurance certificate/Green Card valid

from

2026-01-01

to

2026-12-31

Agency (office or broker)

Name

Address

ul. Pyatnytskaya, d. 12, str. 2, 115035 Moskva

Postcode

Country

Phone/ email

Is damage to the vehicle insured under the policy?

☐ no

☒ yes

9. Driver

(see driving licence)

Surname

Yvanov

First name

Yvan

Date of birth

1980-12-12

Address

Profsoyuznaya ulytsa 42, Moskva

Postcode

117420

Country

RU

Phone/ email

+7 916 123-45-67, ivan.ivanov@example.com

Driving licence no.

RU 5510842


Category (A,B,...)

B

Licence valid until

2028-12-12

10. Indicate with an arrow the point of initial impact on vehicle A



11. Visible damage to vehicle A

14. Remarks

Ya dvyhalsya po ulytse Profsoyuznaya ulytsa pryamo

cherez perekryostok po pravoj polose so skorostyu okolo 40 (...)

3. Injuries

Injured/slightly injured?

☒ no

☐ yes

4. Material damage

to vehicles other than A and B

☒ no

☐ yes

to objects other than vehicles

☒ no

☐ yes

12. Circumstances

Put a cross in each box that applies, to help explain the sketch. Cross out anything that does not apply.

A

01

☐

was parked / was stationary

02

☐

was leaving a parking place / was opening a car door

03

☐

was pulling into a parking place

04

☐

was leaving a car park, private property or a track

05

☐

was entering a car park, private property or a track

06

☐

was entering a roundabout

07

☐

was driving on a roundabout

08

☐

struck the rear of the other vehicle while going in the same direction and in the same lane

09

☐

was going in the same direction, but in a different lane

10

☐

was changing lanes

11

☐

was overtaking

12

☐

was turning right

13

☐

was turning left

14

☐

was reversing

15

☐

was crossing into the oncoming lane

16

☐

was coming from the right (at a junction)

17

☐

had ignored a priority sign or a red light

☐

Enter the number of boxes marked with a cross.

B

01

☐

02

☐

03

☐

04

☐

05

☐

06

☐

07

☐

08

☐

09

☐

10

☐

11

☐

12

☐

13

☐

14

☐

15

☐

16

☒


17

☒

2

13. Sketch of the accident at the moment of impact

Please show: 1. the lane layout 2. the direction of travel of vehicles A and B (with arrows) 3. their position at the moment of impact 4. road signs 5. street names



Both drivers must sign. Signing does not mean admitting liability - it only confirms the personal details and the description of the accident, which speeds up the claims process.

15. Signatures of both drivers

A



B



5. Witnesses

(underline passengers)

Names, addresses, phone numbers

Maryya Smyrnova, +7 916 100-01-11

VEHICLE B

6. Policyholder/Insured

(see insurance certificate)

Surname

Berzins

First name

Janis

Address

Brivibas iela 108, Riga

Postcode

LV-1001

Country

LV

Phone/ email

+371 2123 4567

7.1 Motor vehicle

Make, type

Volkswagen Passat

Registration number

KL-4471

Country of registration

LV

7.2 Trailer

Registration number

Country of registration

8. Insurance company

(see insurance certificate)

Company name

AAS BTA Baltic Insurance Company

Policy number

LV-2026-114770

Green Card number

LV/26/114770

Insurance certificate/Green Card valid

from

2026-02-01

to

2027-01-31

Agency (office or broker)

Name

Address

Sporta iela 11, 1013 Riga

Postcode

Country

Phone/ email

Is damage to the vehicle insured under the policy?

☒ no

☐ yes

9. Driver

(see driving licence)

Surname

Berzins

First name

Janis

Date of birth

1980-07-19

Address

Brivibas iela 108, Riga

Postcode

LV-1001

Country

LV

Phone/ email

+371 2123 4567, janis.berzins@example.com

Driving licence no.

LV 4471820


Category (A,B,...)

B

Licence valid until

2028-07-19

10. Indicate with an arrow the point of initial impact on vehicle B



11. Visible damage to vehicle B

14. Remarks

Tuvojos Profsoyuznaya ulytsa krustojumam no labas puses

pa pakartoto celu. Transportlīdzekli A pamaniju par velu un (...)

easf.eu

| European Accident Statement

English

Annex - additional details

14. Notes (optional) (A)

Ya dvyhalsya po ulytse Profsoyuznaya ulytsa pryamo cherez perekryostok po pravoj polose so skorostyu okolo 40 km/ch. Avtomobyl B vyeahal sprava y ne ustupyl dorohu. Povrezhdeny perednee pravoe krylo, bamper y pravaya fara.

14. Notes (optional) (B)

Tuvojos Profsoyuznaya ulytsa krustojumam no labas puses pa pakartoto celu. Transportlidzekli A pamaniju par velu un nedevu celu. Bojats kreisais sans pie prieksejam durvim. Atzistu savu vainu.